SPEEDY-CLEAN

THE ACID-ALTERNATIVE CONCRETE DISSOLVER

NO SULFURIC ACID

NO MURIATIC ACID

NO HYDROCHLORIC ACID

NO PHOSPHORIC ACID



NON-CORROSIVE

NON-FUMING

NON-FLAMMABLE

100% BIODEGRADABLE

NON-HAZARDOUS TO EQUIPMENT

USE TO CLEAN: CONCRETE SPLASH ON SIDING, FOUNDATIONS
PATIOS & WOODEN DECKS • READY-MIX TRUCKS, MIXERS, VEHICLES •
FORMS, MOLDS. CEMENT BUGGIES, • PUMPS • TROWELS, SCREEDS •
CONCRETE SAWS • SLIP-FORM PAVERS • AUGERS AND MORE!

SPEEDY-CLEAN is a liquid compound specifically formulated to dissolve builtup cement on tools and equipment associated with the concrete ready-mix industry. The highly-concentrated formulation is compounded to maintain sufficient acidity to dissolve hardened cement. The softened concrete substance is then cold-water rinscable with a high-pressure washer.

SPEEDY-CLEAN can be used to remove cured cement, concrete, mortar, grout or stucco from any surface and also removes old rust and oxides.

SPEEDY-CLEAN is also odorless and non-fuming, nonflammable, will not harm paint, is non-corrosive and 100% biodegradable.

Sold By:			

SPEEDY-CLEAN is a liquid compound alternative with no odors of fumes. It attacks the Portland in cement, completely dissolving the hardened cement to a mushy substance that is completely rinseable with high-pressure and cold water. **SPEEDY-CLEAN** can be used to remove cured cement, concrete, mortar, grout or stucco off any surface.

DIRECTIONS FOR USE

IMPORTANT: NEVER WET SURFACE BEFORE APPLYING SPEEDY-CLEAN.

- SPEEDY-CLEAN is most effective when applied with a brush, thereby removing already neutralized cement while at the same time exposing un-neutralized cement to SPEEDY-CLEAN
- Completely saturate area of hardened concrete to be removed with undiluted
 SPEEDY-CLEANthrough an air-foamer, sprayer or soft brush. Surface will turn white on contact, then darken. If SPEEDY-CLEAN evaporates, a white residue will appear. DO NOT RINSE! Re-apply SPEEDY-CLEANto reactivate as needed until concrete has softened to a mush.
- Allow SPEEDY-CLEAN to penetrate for 10-15 minutes. Then re-apply to same area. Keep surface wet with SPEEDY-CLEAN. Concrete will begin to soften and release from surface. (Total time approx. 20-30 min.) Treated concrete can be left overnight.
- Rinse with cold water through a high-pressure washer (1000-3000 psi). On extra-thick buildup, repeat cleaning directions until buildup has softened.

CAUTION: ALWAYS WEAR EYE PROTECTION AND RUBBER GLOVES WHEN HANDLING ANY TYPE OF CHEMICAL.

KEEP OUT OF REACH OF CHILDREN

HMIS RATING:

HEALTH: 2 FLAMMABILITY: 0 REACTIVITY: 0 PERSONAL PROTECTION: C

FIRST AID:

EYES: All exposures are considered severe. Flush thoroughly in an eye wash for 15 minutes. Get medical attention immediately. SKIN: Wash for 5 minutes. INHALATION: If excessive inhalation has occurred, initiate oxygen administration at a 2 to 6 Liter per minute flow. Get medical attention immediately. INGESTION: Do no induce vomiting. Conscious patient: give orally high amounts of water or milk. Obtain medical attention immediately.

DOT HAZARD CLASSIFICATION: Compound, Cleaning Liquid, (Not Regulated)